



Type No.	D1	R	L1	L2	L3	Z
HNMR 1004	1,0	0,1	1,5	50,0	4,0	2
HNMR 1006	1,0	0,1	1,5	50,0	6,0	2
HNMR 1008	1,0	0,1	1,5	50,0	8,0	2
HNMR 1012	1,0	0,1	1,5	50,0	12,0	2
HNMR 1504	1,5	0,1	1,5	50,0	4,0	2
HNMR 1506	1,5	0,1	1,5	50,0	6,0	2
HNMR 1508	1,5	0,1	1,5	50,0	8,0	2
HNMR 1512	1,5	0,1	1,5	50,0	12,0	2
HNMR 2008	2,0	0,2	2,0	50,0	8,0	2
HNMR 2010	2,0	0,2	2,0	50,0	10,0	2
HNMR 2012	2,0	0,2	2,0	50,0	12,0	2
HNMR 2016	2,0	0,2	2,0	50,0	16,0	2
HNMR 2008A	2,0	0,5	2,0	50,0	8,0	2
HNMR 2010A	2,0	0,5	2,0	50,0	10,0	2
HNMR 2012A	2,0	0,5	2,0	50,0	12,0	2
HNMR 2016A	2,0	0,5	2,0	50,0	16,0	2
HNMR 3008A	3,0	0,5	3,0	50,0	8,0	2
HNMR 3012A	3,0	0,5	3,0	50,0	12,0	2
HNMR 3016A	3,0	0,5	3,0	50,0	16,0	2
HNMR 3020A	3,0	0,5	3,0	50,0	20,0	2
HNMR 4012A	4,0	0,5	4,0	50,0	12,0	2
HNMR 4016A	4,0	0,5	4,0	75,0	16,0	2
HNMR 4020A	4,0	0,5	4,0	75,0	20,0	2
HNMR 4025A	4,0	0,5	4,0	75,0	25,0	2
HNMR 4030A	4,0	0,5	4,0	75,0	30,0	2
HNMR 0308	3,0	0,2	3,0	50,0	8,0	2
HNMR 0312	3,0	0,2	3,0	50,0	12,0	2
HNMR 0316	3,0	0,2	3,0	50,0	16,0	2
HNMR 0320	3,0	0,2	3,0	50,0	20,0	2
HNMR 0412	4,0	0,2	4,0	50,0	12,0	2
HNMR 0416	4,0	0,2	4,0	75,0	16,0	2
HNMR 0420	4,0	0,2	4,0	75,0	20,0	2
HNMR 0425	4,0	0,2	4,0	75,0	25,0	2
HNMR 0430	4,0	0,2	4,0	75,0	30,0	2

